

Oil Field Environmental Incident Summary

Incident: 20160824154652 **Date/Time of Notice:** 08/24/2016 15:46

Responsible Party: Condor Petroleum, Inc.

Well Operator: CONDOR PETROLEUM, INC.

Well Name: MELVIN PETERSON 1

Field Name: NORTH TIOGA

Well File #: 1618

Date Incident: 8/23/2016 **Time Incident:** 11:15

Facility ID Number:

County: BURKE

Twp: 159

Rng: 94

Sec: 8

Qtr: SW SW

Location Description: Blew off to the east in the crop field.

Submitted By: Denise Gustafson

Received By:

Contact Person: Denise Gustafson
216 16TH STREET SUITE 1750
DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 2 Mile

Distance Nearest Water Well: 2 Mile

Type of Incident: Other - List Under Desc of Cause below

Release Contained in Dike: No

Reported to NRC: No

| | Spilled | Units | Recovered | Units | Followup | Units |
|-------|---------|-------|-----------|-------|----------|---------|
| Oil | | | | | | |
| Brine | | | | | | |
| Other | | | | | 0 | barrels |

Description of Other Released Contaminant:

Less than one barrel of paraffin with small trace of oil

Inspected:

Written Report Received: 2/9/2017

Clean Up Concluded: 9/19/2016

Risk Evaluation:

none

Areal Extent:

Triangular area approximately 75' x 75' x 75' in wheat field

Potential Environmental Impacts:

none

Action Taken or Planned:

Cleaned work-over rig and location with hot fresh water. Remove damaged crop if landowner requests.

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 8/24/2016 **Status:** Reviewed - Follow-up Required

Author: Schiermeister, Robin

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Corresponded with representative to get more information which revealed that release was not contained to a well pad. The release blew into a neighboring wheat field. Also, the spill was described to be a blowout which, after talking to the representative, was determined to be a rig malfunction that sprayed. More follow-up needed.

Date: 8/30/2016 **Status:** Inspection

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location 13:15, 8/30/2016.

Spray of oil out to the SE of the pump jack into a standing wheat field. No work on cleanup appears to have been done at the time of inspection.

More follow-up is necessary to ensure proper cleanup.

Date: 9/22/2016 **Status:** Inspection

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location 3:53, 9/22/2016.

Impacted area has yet to be cleaned up. Surrounding crop has been harvested. Contact company regarding cleanup.

More follow-up is necessary.